

INDEX:

Page	Article
2	Warranty Repair Claim Procedure
3	Health and Safety Legislati0n
	Warranty Auth0risati0n
4	ASC Training
	Ac0rn Training Schedule
	Events Calender
5	Service of Power Supplies
	SID News
6	New BBC Model B Emulator
7	ChangeFSI
8	FCO2018 - Ethernet
11	FCO2019 - 20 Meg Hard Drive replacements
13	FCO2020 - FileStore E01

Every effort has been made to ensure that the information in this leaflet is true and correct at the Acorn Computers Limited time of printing. However, the products described in this leaflet are subject to continuous Fulbourn Road development and improvements and Acorn Computers Limited reserves the right to change its Cherry Hinton specifications at any tIme. Acorn Computers Limited cannot accept liability for any loss or damage Cambridge CB1 4JN arising from the use of any information or particulars in this leaflet. ACORN, ECONET and ARCHIMEDES are trademarks of Acorn Computers Limited. UNIX is a trademark of AT&T. Telephone (0223) 245200

ETHERNET is a trademark of Xerox Corporation. Telex 8177875 ACORN G Fax (0223) 210685

ISSUE NO. 9

To:

Acorn

Acorn Distributors Acorn Direct Dealers Acorn Approved Service Centres Acorn Central Workshops

December 1990

Dear Colleague,

Acorn Computers Limited FulbOurn Road Cherry Hinton Cambridge CB] 4JN England TelephOne 0223 245200 Telex 817875 ACORN G Fax No 0223 210685

Warranty Repair Claim Procedure

We recently advised you that the procedure for submitting Warranty Claims had undergone some changes, viz.

- RETURN LOCATION now Coral Park Warehouse,
 - COMPLETING DETAIL ON SERVICE REPORTS.
- RETURNS ADEQUATELY PACKAGED, INCLUDING PARTS, AND AFF1XED TO CLAIM,
- NO return to Central Workshop without prior authorisation from Acorn.

Unfortunately, not everyone appears to have read the procedure, and some claims are being received incomplete, and some product (and PCBs) returned to Central Workshops for repair without prior authorisation.

Please read and follow the procedure previously issued.

If you have not received it for some reason, or have mislaid it, please contact Mary Callen on extension 5600 for a further copy. She will also be able to assist in the verification of in-warranty claims, and the authorisation of returns for Central Workshop repair, if required.

As from 10th December 1990, any claim received incorrectly, or product returned without authorisation, will be returned to the sender without attention.

If you should require any further assistance or guidence, please contact me on extension 5381. Yours faithfully,

Rosemary Walker

Warranty Control Office

R.K. belter

News Bulletin

The Information contained the Acorn Customer Service Newsletters is of vital importance to all service engineers. Please ensure that copies are distributed to all your support and service staff.

Health and Safety Legislation.

On 1st April 1990 new Health and Safety regulations came into force which will affect all UK dealers. The new regulations are issued under the "Health and Safety" at Work Act 1974, specifically "The Electricity at Work" Regulations 1989.

Also available from the Health and Safety Executive, is a "Memorandum of Guidance" on the new regulations. We recommend strongly that you obtain a copy of both documents and seek advice from your local Health and Safety office on the implications for your business.

Both of these documents may be obtained via HMSO booksellers.

Warranty Authorisation

All product (or PCBs if applicable) that requires referral to a central workshop for warranty repair must be authorised by Acorn prior to submission. Application for authorisation should be made to the warranty control office tel: $0223\ 245200\ x.\ 5394/5600$. Warranty authorisation will be considered only if the following information is supplied:

- 1. full serial No. of the product concerned;
- 2. PCB serial No. (applicable to Archimedes systems only);
- 3. details of the fault;
- 4. end user's date of purchase.

Once authorisation has been granted a pre-paid label will be issued to cover the transportation cost.

It is important that substantiating documentation accompanies full product as detailed 1 - 3 above. Submission of PCB's for replacement require a fully completed service report in addition to substantiating documentation.

Failure to apply for authorisation, or spurious declarations as detailed 1 - 3 above may result in the sender bearing the cost of repair and transportation.

Review of ASC Training Qualifications

As part of our ongoing policy of ensuring that our customers receive the quality of service to which they are entitled, a review of Acorn Service Centres will be performed in the new year.

As part of this review, we will be seeking clarification that those engineers who attended Acorn service training courses are still with the service organisation.

Where the trained engineer has left a service organisation, it is expected that either the replacement engineer or another engineer within the organisation will attend appropriate training course(s).

It is not considered an acceptable situation for an ASC to service without an Acorn trained engineer on the premises, and as such any ASC who no longer has a fully trained member of staff should take action to correct the shortfall please refer to the training schedule below details of training dates.

Acorn Training Courses

There are still places available on several training courses scheduled for November and December. If you wish to apply for a course or if you would like further information, please contact Val Raworth at the Acorn Training Centre (0223 214411). All prices include VAT. The following courses have places available:

A3000/Archimedes Servicing to Module Level (SA2).

Duration: 2 days Cost: £92.00 Dates: 21 - 22 November, 5 - 6 December

A3000/Archimedes Servicing to Component Level (SC/1).

Duration: 1 day Cost: £115.00

Dates: 7 December

Dealer Induction (dealers only) (DI/2).

Duration: 2 days Cost £115.00 Dates: 19 - 20 November, 3 - 4 December

Events Calendar.

Acorn will be present at the following event in 1990.

COMPUTER SHOPPER 6, 7, 8 December Wembley Conference Centre, London

Service of Power Supplies

As a result of a number of requests for information on the repair of PSU's, we would like to remind you that All PSU's fitted to Acorn equipment are deemed NON SERVICABLE items.

In the event of a PSU failure, irrespective of whether the fault is identified e.g a blown fuse, the PSU must be replaced. Acorn will not entertain any claim for payment for the repair of a PSU.

The only exception to the above is where it is identified that a crimp on a flying lead has an unreliable connection. In these circumstances, you are allowed to correct the problem by applying solder to the joint between the cable and the crimp.

Note that this only applies to the crimps on the main PCB end of the flying leads, not the crimps internal to the PSU. Also, soldering is the only method to be applied. No attempt should be made to strip and re-crimp the lead. If soldering the crimp/lead connection does not solve the problem, replace the entire PSU.

Safety Testing

Where a PSU has been replaced, ensure that both an Earth bond test, and 500V DC Insulation breakdown test are applied to the reassembled system. Do not apply any high voltage AC tests i.e Flash Test to the PSU since this may well damage the suppression capacitors on the input side of the PSU.

Full details of the nature of the various safety tests that must be applied to repaired systems will shortly be published in this news letter.

Support Information Database

Do Y 0 U have a SID account yet

If you haven't, what do you do when a customer comes in asking for a piece of software which they know is available on SID?

If you haven't, what do you do when you want a piece of support software urgently from Acorn?

If you have, are there any changes you'd like to see in SID? If you have let your SID subscription lapse tell us why.

Write to the SID Editor, at our Fulboum Rd office.

BBC B Emulator

Acorn has developed an enhanced Model B emulator for RISC OS. This has been made available at a special discount for use in Educational institutions in the UK and for Software Developers registered with Acorn. Teachers should approach their local LEA or IT centre for further information.

Subscribers to SID (Acorn's Support Information Database) can download a copy of the software and all the other parts normally supplied on the disc. The software can also be obtained on disc for people who do not have access to SID.

The disc comprises:

- * improved version of !65Host, which emulates the BBC Model B environment;
- * utilities such as DFS converters, picture converters to transfer BBC screens to the Acorn Archimedes or BBC A3000 and a program which will scan your BBC BASIC programs and check for any possible problems areas in them which will cause problems when porting the programs across, all these utilities are designed to help transfer and modify 6502-based programs for use with RISC OS computers;
- * examples to illustrate how to port existing 6502-based programs onto RISC OS;
- * comprehensive User Guide in electronic format(Text and Acorn DTP).

To obtain a copy of the software on disc, send:

- * your name and address;
- * a cheque or postal order for £19.55 (which includes VAT and postage) made payable to Acorn Direct;

to:

13 Dennington Road WELLINGBOROUGH Northants NN8 2RL

This is a special and limited offer by Acorn Computers Ltd and is not supported by Acorn or its dealer network. This does not infringe your statutory rights.

ChangeFSI: Colour Image Processing Using a fixed set of 256 colours

Archimedes computers have full colour display capabilities built into them as standard. However, compared with the hardware found in larger workstations, the facilities provided have been carefully reduced (in order to make them cheap enough to fit all the time). So the precision of the digital to analog converters is only 4 bits (instead of 8) and the colour palette only has 16 entries (instead of 256).

This leads to a conversion problem for colour images built on other machines. The solution involves colour Floyd Steinberg error diffusion to a fixed colour palette and has implications for other machines, especially when sequences of images or many images shown on the same display are concerned.

In addition to solving this particular problem, a number of conventional image enhancement algorithms (sharpening, dynamic range expansion, histogram equalisation) and an "equal area" anti-aliased size scaling routine are all incorporated in the same step, giving a maximal quality output.

The following image formats are supported by ChangeFSI:

RISC OS 1, 2, 4 and 8 bit per pixel sprites

Watford digitiser pictures 512x256y64g and triple red, green, blue separations

ProArtisan compressed pictures 640x256y256c

TimeStep satellite image 800x800y256g

TimeStep satellite image 128x256y256g and triple red, green, blue separations

!Translator "Clear" format

AIM/Wild Vision Hawk V10 files 256x256y256g

lit___pictures 1-24 bits per pixel

Electronic Art's IFF ILBM pictures

Sun 'pixrect' raster files 1-24 bits per pixel

.PIC 8 bit per pixel files

MILLIPEDE PRISMA 768x574y 8 bit colour images

Compuserve's GIF files up to 8 bit per pixel

ZSoft PCX format 4/8 bit per pixel

MacPaint files 576x720y 1 bit per pixel

Windows 3 .BMP format 1/4/8 bits per pixel

Degas 1/2/4 bits per pixel colour images

Truevision "Targa" (both TGA and VDA)

Wild Vision V9 Colour images 512x256y12 bits

ArVis 15 bit HIP.+LOP. sprites 640x256v

Pineapple 16 bit colour images 512x256y

GEM IMG. images

UNIX "rle" files

PC EGA .DSP images 640x350y16c

MTV 24 bit pic. images

QRT 24 bit .raw images

RT 24 bit run length coded image. files

Subscribers to SID (Acorn's Support Information Database) can download a copy of the software and all the other parts normally supplied on the disc. The software can also be obtained on disc for people who do not have access to SID.

ChangeFSI can also be obtained on disc, by sending a cheque made payable to Acorn Direct for £19.55 (inc. VAT & **P+P**) from the Acorn direct address on the previous page.

FIELD CHANGE ORDER ACORN COMPUTERS LTD

Field Change Order No.	2018
Date of Issue.	17th July 1990
Applicable to (Product)	Ethernet 1 - AKA25

Reason for Issue

Unrelibity can be caused when Ethernet 1 is used with other expansion cards that also use the CLK8 signal due to loading. Changing IC 18 from a 74 ACT 240 to a 74 AC 240 improves immunity by raising the logic threshold from TTL to CMOS levels.

Types Affected (e.g. Serial Nos / Issues Levels)

See attached pages for serial number ranges.

Description of Change

Remove IC 18 (74 ACT 420) and replace with 74AC240 (Acom approval No. 0750,240).

Claim Procedure

Following completion of the Field Change Order instructions, Service Engineers should fill out a Service Report clearly stating the Serial No. of the Host unit, the FCO No. (above), and claim the FCO Credit Rate (below) for labour charges. Any replaced components should be wrapped to ensure safe carriage and returned with the Service Report. Acorn will verify the information, process the claim for labour charges in the normal manner and issue any replacement components as necessary.

Rework	Doc.	Referer	ıce
(SID Doc ret	1		

FCO Credit Rate

£ 16.00 (Sixteen)

Special Instructions:-

ECO 2019	1000441
FCO 2018	1000441
01 AV A25 (Filterest)	
01 AKA25 (Ethernet) - serial number of	1000446 - 1000447
machines not reworked by Callfind.	1000449 - 1000450
	1000452
1000001 - 1000037	1000461
1000039 - 1000074	1000465
1000076 - 1000077	1000468
1000079 - 1000081	1000472 - 1000474
1000083 - 1000091	1000476
1000093 - 1000100	1000484 - 1000487
1000102- 1000108	1000492
1000112 - 1000113	1000494 - 1000496
1000115	1000498
1000117	1000500
1000119 - 1000120	1000504
1000123	1000507 - 1000509
1000125	1000507 1000503
1000132 - 1000133	1000512
1000137 - 1000138	1000518 - 1000521
1000141 - 1000142	1000513 - 1000521
1000145 - 1000149	1000554 - 1000564
1000151 - 1000152	1000566
1000154 - 1000156	1000568 - 1000573
1000158	1000575 - 1000576
1000160 - 1000163	1000578
1000165 - 1000169	1000576
1000171 - 1000175	1000590 - 1000594
1000177 - 1000180	1000596
1000182 - 1000187	1000598
1000190- 1000222	1000600 - 1000604
1000225 - 1000228	1000609
1000230	1000612 - 1000673
1000232 - 1000286	1000676 - 1000679
1000288 - 1000289	1000670 - 1000675
1000291 - 1000296	1000684 - 1000685
1000301	1000692 - 1000695
1000305 - 1000306	1000700
1000303 - 1000300	
1000314 - 1000314	1000702 1000708 - 1000710
1000320 - 1000326	
1000322 - 1000320	1000717
1000331 - 1000330	1000720
1000340 - 1000340	1000724
1000406	1000733
1000400	1000735
1000408	1000738
1000410 - 1000411	1000740
1000413	1000759
1000422	1000772 - 1000854
1000426	1000867
1000428 - 1000430	1000909
1000730	1000914

1001289

FIELD CHANGE ORDER ACORN COMPUTERS LTD

Field Change Order No. 2019	
Date of Issue.	August 1990
Applicable to (Product)	(AKB20), A420/1 (AKB42), AKD52

Reason for Issue

Latest source of 20 Meg hard disc drive is both mechanically different and requires a previously unspecified set of HForm parameters to ensure correct formating.

Types Affected

(e.g. Serial Nos / Issues Levels)

Any A440 (AKB20), A420/1 (AKB42) & AKD52 requiring hard disc replacement.

Description of Change

When using 20MB hard drives from Component Approval 0912,014 (Kalok KL320) in the above machines the additional instructions on sheet 2 must be followed.

Claim Procedure

Not applicable

Rework Doc. Reference

(SID Doc ref.) FCO2019

FCO Credit Rate

Null: information only

Special Instructions:

The above is supplied for information only. All replacement Kalok drives will be supplied with the above information.

FCO2019: Sheet 2

A420/1, A440 and AKD52(Hard drive upgrade 300 series)

USE OF KALOK KL320 HARD DISC DRIVES.

When Kalok KL320 hard drives to Acorn Approval 0912,014 are used in A42011 (AKB42) or A440 (AKB20) computers as field replacements for either of the existing sources, the following instructions must be followed.

ASSEMBLY

Fit an M3.5 plain washer under the head of each of the four screws used to secure the drive to the -- drive bracket in addition to the existing spring washer.

FORMATING

When formating the hard disc drive using HForm Version 1.78 (or earlier) the shape of the Kalok drive will not be recognised and the following parameters must be entered after the prompts shown-

Which make of hard disc (1-6)?	6 (other
Old or New map format (O/N)?	N
Sectors per track?	32
Heads?	4
Cylinders?	615
Low current cylinder?	1023
Precompensation cylinder?	300
Parking cylinder?	615

The drive should undergo a full 24hour soak test cycle before being returned to the customer.

FIELD CHANGE ORDER ACORN COMPUTERS LTD

Field Change Order No.	2020
Date of Issue.	28th August 1990
Applicable to (Product)	Filestore E01

Reason for Issue

Design error: Bi-phase network clock is 180 degrees out of phase with clocks generated by Econet Clock Boxes and E01S Filestores. Consequently the system fails to recognise the presence of an external clock (when these are installed in large networks). This can cause unreliable network data transfer.

Types Affected (e.g. Serial Nos / Issues Levels)

All product.

M Series (AEH26 - 0354, 002) C Series (AEH26 - 0354, 000)

Description of Change

On COMPONENT side of PCB: cut 2 tracks - IC26 pin 14 to SK10 pin 4 IC26 pin 15 to SK10 pin 5

On SOLDER side of PCB: link as follows IC26 pin 14 to SK10 pin 5 IC26 pin 15 to SK10 pin 4

Claim Procedure

Following completion of the field change order instructions, service engineers should fill out a service report clearly stating the serial no. of the host unit, the FCO No. (above), and claim the FCO credit Rate (below) for labour charges. Any replaced components should be wrapped to ensure safe carriage and returned with the service report. Acorn will verify the information, process the claim for labour charges in the normal manner and issue any replacement components as necessary.

Rework Doc. Reference	FCO Credit Rate
(SID Doc.ref.) FCO2020	£ 16.00 (sixteen)

Special Instructions:-

None