

Addendum - Please Read

Due to product changes the IIC connector is no longer fitted to the Morley Analogue and User Port upgrade. Page 9 is therefore no longer applicable and should be ignored.