

Release Note Addendum

Defects on Conner CFS541A, CFS1081A and CFS1621 A Disc Drives

Desktop Verify and *Verify will incorrectly report addresses of defects on some disc drives including the Conner drives above. Defects addresses when attempting to access a file will be reported correctly.

The utility !Verify in the Diversions.Tools directory can be used instead of *Verify or Desktop Verify and the addresses reported will be correct on both the above Conner drives and other drives shipped by Acorn.

Help on using !Verify is available via the filer Help menu option.