


# RISC OS 3 software upgrade fitting instructions: Errata

## Incorrect diagrams

Please note that the diagrams on pages 20 and 32 are incorrect, showing the ROMs the wrong way round, although the text does describe the correct way to fit the ROMs. The correct diagrams are included below.

Archimedes 540 and Acorn R260 computers


This is the correct diagram for page 20:



*Incorrect diagrams*

Acorn A5000 computer

This is the correct diagram for page 32:



0496,079 - 01 September 1992.